FRONT PAGE

BUYERS GUIDE

IMPORTANT: Spoken promises are difficult to enforce. Ask the dealer to put all promises in writing. Keep this form.

Honda

CR-V

2005

JHLRD68575C013156

VEHICLE MAKE

MODEL

YEAR

VEHICLE IDENTIFICATION NUMBER (VIN)

WARRANTIES FOR THIS VEHICLE:

X	AS IS - NO DEALER WARRANTY THE DEALER DOES NOT PROVIDE A WARRANTY FOR ANY REPAIRS AFTER SALE.
	DEALER WARRANTY
I	☐ FULL WARRANTY.
I	LIMITED WARRANTY. The dealer will pay% of the labor and% of the parts for the covered systems that fail during the warranty period. Ask the dealer for a copy of the warranty, and for any documents that explain warranty coverage, exclusions, and the dealer's repair obligations. <i>Implied warranties</i> under your state's laws may give you additional rights.
SYSTEMS COVERED: DURATION:	
NON-DEALER WARRANTIES FOR THIS VEHICLE:	
	MANUFACTURER'S WARRANTY STILL APPLIES. The manufacturer's original warranty has not expired on some components of the vehicle.
	MANUFACTURER'S USED VEHICLE WARRANTY APPLIES.
	OTHER USED VEHICLE WARRANTY APPLIES.
	k the dealer for a copy of the warranty document and an explanation of warranty coverage, exclusions, and repair igations.
	SERVICE CONTRACT. A service contract on this vehicle is available for an extra charge. Ask for details about coverage, deductible, price, and exclusions. If you buy a service contract within 90 days of your purchase of this vehicle, <i>implied warranties</i> under your state's laws may give you additional rights.

ASK THE DEALER IF YOUR MECHANIC CAN INSPECT THE VEHICLE ON OR OFF THE LOT.

OBTAIN A VEHICLE HISTORY REPORT AND CHECK FOR OPEN SAFETY RECALLS. For information on how to obtain a vehicle history report, visit ftc.gov/usedcars. To check for open safety recalls, visit safercar.gov. You will need the vehicle identification number (VIN) shown above to make the best use of the resources on these sites.

SEE OTHER SIDE for important additional information, including a list of major defects that may occur in used motor vehicles.

Si el concesionario gestiona la venta en español, pídale una copia de la Guía del Comprador en español.

Year: 2005 Make: Honda Model: CR-V VIN: JHLRD68575C013156

Here is a list of some major defects that may occur in used vehicles.

Frame & Body

Frame-cracks, corrective welds, or rusted through

Dog tracks-bent or twisted frame

Engine

Oil leakage, excluding normal seepage Cracked block or head Belts missing or inoperable

Knocks or misses related to camshaft

lifters and push rods

Abnormal exhaust discharge

Transmission & Drive Shaft

Improper fluid level or leakage, excluding normal seepage

Cracked or damaged case which is visible Abnormal noise or vibration caused by faulty transmission or drive shaft

Improper shifting or functioning in any gear Manual clutch slips or chatters

Differential

Improper fluid level or leakeage, excluding normal seepage

Cracked of damaged housing which is visible

Abnormal noise or vibration caused by faulty differential

Cooling System

Leakage including radiator Improperly functioning water pump

Electrical System

Battery leakage

Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories

Gauges or warning devices Air conditioner

Heater & Defroster

Brake System

Failure warning light broken
Pedal not firm under pressure (DOT spec.)
Not enough pedal reserve (DOT spec.)
Does not stop vehicle in straight line
(DOT spec.)

Hoses damaged

Drum or rotor too thin (Mfgr. Specs) Lining or pad thickness less than 1/32 inch Power unit not operating or leaking Structural or mechanical parts damaged

Air Bags

Steering System

Too much free play at steering wheel (DOT specs.)
Free play in linkage more than 1/4 inch Steering gear binds or jams

Front wheels aligned improperly (DOT specs.)

Ball joint seals damaged

Power unit belts cracked or slipping Power unit fluid level improper

Suspension System

Structural parts bent or damaged Stabilizer bar disconnected Spring broken Shock absorber mounting loose Rubber bushings damaged or missing Radius rod damaged or missing Shock absorber leaking or functioning improperly

Tires

Tread depth less than 2/32 inch Sizes mismatched Visible damage

Wheels

Visible cracks, damage or repairs Mounting bolts loose or missing

Exhaust System

Leakage

Catalytic Converter

DEALER NAME

Rick Austin Automotive, Inc.

ADDRESS

22002 State Hwy. 249 Houston ,TX 77070

TELEPHONE

EMAIL

(281) 376-6071

raassbs@yahoo.com

FOR COMPLAINTS AFTER SALE, CONTACT:

Rick Austin Automotive, Inc. -

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).